



Accesorios para cables y cadenas:

TENSORES DE CAJA ABIERTA

Medida D y L	L1 mm.	L2 mm.	e mm.	e1 mm.	C mm.	D mm.	A mm.	Peso aprox. x 100 pcs.	Carga de trabajo
M6 x 100 mm	83	80	50	50	8	20	9	11	100
M8 x 125 mm	93	84	62.5	62.5	10.5	22	10	20	200
M10 x 150 mm	123	105	75	75	13	31	14	28	300
M12 x 200 mm	130	110	100	100	16	35	16	43	500
M16 x 250 mm	167	143	125	125	19	47	22	100	1000
M20 x 200 mm	198	165	150	150	21	52	24	160	1500
M22 x 330 mm	223	185	165	165	24	60	28	220	2200
M24 x 350 mm	245	208	175	175	26	65	28	280	3000



Tipo A: Ojo y horquilla



Tipo B: Ojo y ojo



Tipo C: Horquilla y horquilla



Tipo D: Gancho y gancho



Tipo E: Horquilla y gancho



Tipo F: Gancho y ojo